


MOTHERBOARD CPU SOCKET REPINING



Damaged pins within the motherboard CPU socket are considered physical damage and is therefore not covered under warranty.

Some manufacturers can replace the CPU socket for a fee. The below table outlines the charges involved and the expected turnaround times.

Brand	Cost	Turnaround	Notes
Asrock	N/A	N/A	No repining option available.
Asus	\$75 Inc GST	4-6 weeks	Customer should pay these charges in advance.
Gigabyte	\$75 Inc GST	4-6 weeks	
MSI	\$75 Inc GST	4-6 weeks	

If the customer agrees to these charges please book the damaged motherboard into the warranty database and transfer it back to the warranty department for processing.

This document is for internal staff use only.

If you have any questions regarding the above please email warranty@centrecom.com.au